ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra

Street ID	Street Name	Significant Landmark
W0316, W0300, W0585, W0589, W0587, W0583	Chikkanna Lyt 2nd Crs, 4th Crs Lakshmi Sagar Lyt, 1st Crs, 7th Crs, 3rd Crs	Buddisht School (Dasarahalli Extension)

Segment No.	Total Length (m)
6/C-W0316/S034509	320.41

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	92.61	77.610202	13.060170	77.610830	13.060416	M0013	W0300
2	227.80	77.609454	13.061061	77.610830	13.060444	M0013	W0316

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains Near Buddisht School (Dasarahalli Extension) in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	3000000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvement to Roads and Drains Near Buddisht School (Dasarahalli Extension) in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000032

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/14/2015-16	30/04/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/04/2016	29/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
NITHIN.R		0.00

Phone No.	E-Mail ID
9341260169	

Field Inspection Details

Number of Trees	Any Other Information	Name
10		KRISHNAPPA
Date of Inspection	**Remarks**	
26/11/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0316, W0300, W0585, W0589,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0316, W0300, W0585, W0589,

SE	VASU K M	26/11/2016	26/12/2016	COMPLETED
EE	YARAPPA REDDY	26/11/2016	26/12/2016	COMPLETED
AEE	J N LOKESH	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0316, W0300, W0585, W0589,